

Zpráva o inspekci fotovoltaické elektrárny FVE - nová instalace na střeše ze dne 23. 2. 2024

Defect ID	Anomaly name	Main image ID	Linked image ID	Main image filename	Linked image filename	Datetime	Section ID	Row X,Y	Row letter	String X,Y	Module X,Y	Priority	Temp. min (°C)	Temp. max (°C)	Temp. mean (°C)	Temp. delta (°C)
5780774	Module	70750421	70750423	DJI_20240216155306_0025_T.JPG	DJI_20240216155306_0025_W.JPG	2024-02-16 14:53:06+01:00		0,0		0,0	4,7	3				
5780779	Cell Multi Low	70750421	70750423	DJI_20240216155306_0025_T.JPG	DJI_20240216155306_0025_W.JPG	2024-02-16 14:53:06+01:00		0,0		0,0	2,2	1	25.5	32.6	25.7	6.9
5780782	Cell Multi Low	70750421	70750423	DJI_20240216155306_0025_T.JPG	DJI_20240216155306_0025_W.JPG	2024-02-16 14:53:06+01:00		0,0		0,0	1,4	1	25.3	29.5	25.6	3.9
5780788	Cell Multi Low	70750421	70750423	DJI_20240216155306_0025_T.JPG	DJI_20240216155306_0025_W.JPG	2024-02-16 14:53:06+01:00		0,0		0,0	2,1	1	26.1	28.2	26.3	1.9
5780885	String	70750429	70750432	DJI_20240216155144_0022_T.JPG	DJI_20240216155144_0022_W.JPG	2024-02-16 14:51:44+01:00		0,0		0,0	6,17	3				